

Attachment G

Summary of Distribution Circuit Field Inspection by ICC Staff			
Utility:	IP	Date:	6/12/02
Circuit:	Bloomington 240 (Hudson rural)	Inspector:	J. D. Spencer, Bev Hall (IP)
Gen. Notes: Many of the roads and streets were not labeled on the circuit maps provided, making the maps more difficult to follow. Some relatively small sections of this circuit are cross-country and inaccessible.			
<i>Map No.</i>	<i>Item Description</i>	<i>Photo(s)</i>	<i>Location</i>
1 of 10	Bad crossarms & broken ground wire	B22, B23, B25, C1	Corner of CH 8 & road not labeled on map (Point 04994D)
1	Bad crossarm	B24	1st pole west of corner of CH 8 & road not labeled on map (Point 04994E)
1	Oak limbs between single phase primary conductor & neutral	C2, C3	Span between Stas. 21650 & 14777 (road not labeled on map), west of CH 8
1	Missing guy marker		On CH 8 at 2nd pole from NE corner of map
3	Leaning primary pin		On east side of CH 8 south of Hepatica Ln. (not labeled on map)
3	Large broken limb high above transformer (wedged in tree)		At Sta. 18173 on White Owl Ln. (not labeled on map)
4	Missing guy marker		At Sta. 12117 north of Lake Bloomington (roads not labeled on map)
6	Missing guy marker		At Sta. 20121 at south edge of map
6	Missing guy marker		1st pole east of Sta. 12136 at south edge of map
6	Missing guy marker		At Sta. 16833 west of CH 31
6	Split crossarm		At Sta. 12142 on CH33 east of Rd. 1740E
7	Broken ground wire at top of pole		At Sta. 22675 on CH 33 west of Smith St.
7	NESC violation: Microwave antenna too close to energized primary (about one foot below primary & between primary & neutral)	B19, B20, B21	Across from 17982 Carver Rd., CH 33 west of Smith St.
7	Split pole top		1st pole east of Smith St. on CH 33 (Carver Rd.)
7	Split crossarm		1st pole east of Camp Peairs Rd. (not labeled on map) on CH 33
7	Broken wood pin		1st pole south of Sta. 14044 (streets not labeled on map)